




V a l - C o
People. Products. Solutions.

www.valcompanies.com

Wire Requirements

INSTALATION	WIRES
Power Supply	Three Wires: Ground Neutral Phase
Temperature Sensor	Three Wires: (+) White 18/3 SHIELED (s) Red (-) Black
Load Cell (Scales)	Three Wires: (+) Red 18/3 SHIELED (s) White (-) Black
Water Counter or Feed Counter	Two Wires: (+) not connected (s) White 16/2 SHIELED (-) Black



Thermometer Leads: Brown to Black of Cable
 : Green to Red of Cable
 : White to White of Cable